

**RESPONSE TO ASH POND OBSERVATIONS AND RECOMMENDATIONS PER
AECOM'S EAST ASH POND VISUAL SITE INSPECTION REPORT - 2018**

Documented to meet 257.83(b)(5)

	DEFICIENCY/OBSERVATION (inspection recommendation #)	CORRECTIVE MEASURE
1	Minor erosion rills on embankments on the downstream side of the crest's edge.	The area was regraded.
2	Area around a recently installed piezometer does not have vegetation or other erosion protection.	The area was regraded.
3	A small tree is present on the eastern embankment of the pond.	Tree removed and the hole was filled with soil and compacted. Rock was then spread over the area.