

**RESPONSE TO ASH POND OBSERVATIONS AND RECOMMENDATIONS PER
AECOM'S WEST ASH POND VISUAL SITE INSPECTION REPORT - 2018**

Documented to meet 257.83(b)(5)

	DEFICIENCY/OBSERVATION (inspection recommendation #)	CORRECTIVE MEASURE
1	Exterior Slope - A few small trees, bushes, and brush have grown on the embankment slope.	Small trees/shrubs have been cut down.
2	Exterior Slope - Concrete stairs leading to the Ohio River are dilapidated. Unstable terrain underlies collapsing stairs.	Damaged stairs removed and area regraded.